


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-262	Smoke	9/1/2009	ADS/TM	S21KK_016MH	Dry	Yes	955.93



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-262	Smoke	9/1/2009	ADS/TM	S21KK_016MH	Dry	Yes	955.93

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S21KK_008G1	S21KK_008MH	S21KK_022MH	112.814	15
S21KK_022G1	S21KK_022MH	S21KK_035MH	189.315	15
S21KK_035G1	S21KK_035MH	S21KK_029MH	60.0223	15
S21KK_050G1	S21KK_050DE	S21KK_032MH	44.6502	8
S21KK_032G1	S21KK_032MH	S21KK_022MH	67.966	8
S21KK_016G1	S21KK_016MH	S21KK_032MH	74.3827	8
S21KK_026G1	S21KK_026MH	S21KK_016MH	406.778	8

Observations & Photos

Obs_ID S1028-262-OB01

Address 2614 Pennsylvania Ave

Status Private

Source Service Lateral

Location Field / woods

Nearest MH S21KK_028MH

Comments Smoke from service lateral in open field near brake shop. 2614 Pennsylvania Ave.



Picture \S1028-262-OB01-P01.jpg

Comments Back of lot, 2614 Pennsylvania Ave.

Obs_ID S1028-262-OB02

Address 1607 Clifton Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S21KK_032MH

Comments Smoke from cleanout in back yard. 1607 Clifton Ave.



Picture \S1028-262-OB02-P01.jpg

Comments Back of house, 1607 Clifton Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-262	Smoke	9/1/2009	ADS/TM	S21KK_016MH	Dry	Yes	955.93

Obs_ID S1028-262-OB03

Address 1615 Clifton Ave

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S21KK_022MH

Comments Smoke from service lateral in back yard. 1615 Clifton Ave.



Picture \S1028-262-OB03-P01.jpg

Comments Back of house, 1615 Clifton Ave.

Obs_ID S1028-262-OB05

Address 2039 Fulton Ave

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S21KK_022MH

Comments Smoke from cleanout in paved concrete behind house. 2039 Fulton Ave.



Picture \S1028-262-OB05-P01.jpg

Comments Back of house, 2039 Fulton Ave.

Obs_ID S1028-262-OB04

Address 1617 Clifton Ave


Status Private

Source Building Interior

Location Other

Nearest MH S21KK_022MH

Comments Smoke from building interior. 1617 Clifton Ave.



Picture \S1028-262-OB04-P01.jpg

Comments Back of house, 1617 Clifton Ave.

Obs_ID S1028-262-OB06

Address 2021 Fulton Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S21KK_022MH

Comments Smoke from cleanout in back yard. 2021 Fulton Ave.



Picture \S1028-262-OB06-P01.jpg

Comments Back of house, 2021 Fulton Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-262	Smoke	9/1/2009	ADS/TM	S21KK_016MH	Dry	Yes	955.93

Obs_ID S1028-262-OB07

Address 2015 Fulton Ave

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S21KK_035MH

Comments Smoke from cleanout in paved concrete behind house. 2015 Fulton Ave.



Picture \S1028-262-OB07-P01.jpg

Comments Back of house, 2015 Fulton Ave.